

**Supported Versions for BB5 Box with Firmware version 6**  
**(total 114 supported models/versions)**

**3109c (RM-274)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05.30_16-05-07_RM-274_(c)_Nokia.	RM-274_DP20_1.00_sw-05.30.exe

**3110c (RM-237)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.91_03-04-07_RM-237_(c)_Nokia.	RM-237_DP20_1.00_sw-04.91.exe
V_05.01_21-05-07_RM-237_(c)_Nokia.	RM-237_DP20_2.00_sw-05.01.exe

**5200 (RM-174) – Flash Chip SEC xxxxxxxx-ATB**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_22-09-06_RM-174_(c)_Nokia.	RM-174_DP20_1.00_sw-03.70.exe
V_03.92_13-10-06_RM-174_(c)_Nokia.	RM-174_DP20_2.00_sw-03.92.exe
V_04.71_28-02-07_RM-174_(c)_Nokia.	RM-174_DP20_3.00_sw-04.71.exe
V_05.00_27-04-07_RM-174_(c)_Nokia.	RM-174_DP20_4.00_sw-05.00.exe

**5200 (RM-174) – Flash Chip SEC xxxxxxxx-ATD**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.92_13-10-06_RM-174_(c)_Nokia.	RM-174_DP20_2.00_sw-03.92.exe
V_04.71_28-02-07_RM-174_(c)_Nokia.	RM-174_DP20_3.00_sw-04.71.exe
V_05.00_27-04-07_RM-174_(c)_Nokia.	RM-174_DP20_4.00_sw-05.00.exe

**5200b (RM-181) – Flash Chip SEC xxxxxxxx-ATB**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_22-09-06_RM-174_(c)_Nokia.	
V_03.92_13-10-06_RM-181_(c)_Nokia.	
V_04.71_28-02-07_RM-181_(c)_Nokia.	
V_05.00_27-04-07_RM-181_(c)_Nokia.	

**5200b (RM-181) – Flash Chip SEC xxxxxxxx-ATD**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.92_13-10-06_RM-181_(c)_Nokia.	
V_04.71_28-02-07_RM-181_(c)_Nokia.	
V_05.00_27-04-07_RM-181_(c)_Nokia.	

**5300 (RM-146) – Flash Chip SEC xxxxxxxx-ATB**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.92_13-10-06_RM-146_(c)_Nokia.	RM-146_DP20_2.00__sw-03.92.exe
V_04.51_11-01-07_RM-146_(c)_Nokia.	RM-146_DP20_2.20_MCU SW 3.92 & 4.51.exe
V_04.70_24-01-07_RM-146_(c)_Nokia.	RM-146_DP20_3.00__sw-04.70.exe
V_04.71_28-02-07_RM-146_(c)_Nokia.	RM-146_DP20_3.10__sw-04.71.exe
V_05.00_27-04-07_RM-146_(c)_Nokia.	RM-146_DP20_4.00__sw-05.00.exe

**5300 (RM-146) – Flash Chip SEC xxxxxxxx-ATD**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.92_13-10-06_RM-146_(c)_Nokia.	RM-146_DP20_2.00__sw-03.92.exe
V_04.51_11-01-07_RM-146_(c)_Nokia.	RM-146_DP20_2.20_MCU SW 3.92 & 4.51.exe
V_04.70_24-01-07_RM-146_(c)_Nokia.	RM-146_DP20_3.00__sw-04.70.exe
V_04.71_28-02-07_RM-146_(c)_Nokia.	RM-146_DP20_3.10__sw-04.71.exe
V_05.00_27-04-07_RM-146_(c)_Nokia.	RM-146_DP20_4.00__sw-05.00.exe

**5300b (RM-147) – Flash Chip SEC xxxxxxxx-ATB**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.92_13-10-06_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_04.51_11-01-07_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_04.70_24-01-07_RM-147_(c)_Nokia.	
V_04.71_28-02-07_RM-147_(c)_Nokia.	
V_05.00_27-04-07_RM-147_(c)_Nokia.	

**5300b (RM-147) – Flash Chip SEC xxxxxxxx-ATD**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.92_13-10-06_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_04.51_11-01-07_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_04.70_24-01-07_RM-147_(c)_Nokia.	
V_04.71_28-02-07_RM-147_(c)_Nokia.	
V_05.00_27-04-07_RM-147_(c)_Nokia.	

**6085 (RM-198)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.71_30-11-06_RM-198_(c)_Nokia.	RM-198_13.00.exe
V_04.26_16-03-07_RM-198_(c)_Nokia.	RM-198_14.0_APAC_EMEA_US_LTA.exe

**6086 (RM-198)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
* <a href="#">V_03.51_15-02-07_RM-188_(c)_Nokia.</a>	<a href="#">RM-188_EMEA_LTA_NA_2.00.exe</a>

**6126/6133 (RM-126)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.24_04-07-06_RM-126_(c)_Nokia.	RM-126_DP20_1.00__sw-04.24.exe
V_05.61_14-12-06_RM-126_(c)_Nokia.	RM-126_DP20_2.00__sw-05.60_05.61.exe

**6131 (RM-115)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05.50_20-09-06_RM-115_(c)_Nokia.	RM-115_DP20_3.00__sw-05.50.exe
V_04.10_21-12-06_RM-200_(c)_Nokia	RM-115_DP20_4.00_sw-06.10.exe

**6136 (RM-199)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.71.2_12-09-06_RM-199_(c)_Nokia.	RM-199_EMEA_5.00.exe

**6151 (RM-200)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.91_25-09-06_RM-200_(c)_Nokia	RM-200_dp_v_72.0_mcusw03.91.exe
V_04.10_21-12-06_RM-200_(c)_Nokia	RM-200_dp_v_81_0_mcusw04_10.exe

**6233 (RM-145) – Flash Chip SEC xxxxxxxx-ETM**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
* <a href="#">V_05.10_21-12-06_RM-145_(c)_Nokia</a>	<a href="#">RM145_CareDP_138.0_SW05.10.exe</a>

**6233 (RM-145) – Flash Chip SPANSION**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_15-05-06_RM-145_(c)_Nokia	RM-145_dp_v_78.0_mcusw03.70.exe
V_04.52_06-07-06_RM-145_(c)_Nokia	RM-145_dp_v_95.0_mcusw04.52_04.54.exe
V_04.54_01-08-06_RM-145_(c)_Nokia	RM-145_dp_v_95.0_mcusw04.52_04.54.exe
V_04.91_25-09-06_RM-145_(c)_Nokia	RM-145_dp_v_122.0_mcusw04.91.exe
V_05.10_21-12-06_RM-145_(c)_Nokia	RM145_CareDP_138.0_SW05.10.exe

**6234 (RM-123) – Flash Chip SEC xxxxxxxx-ETM**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
* <a href="#">V_05.10_21-12-06_RM-145_(c)_Nokia</a>	<a href="#">RM145_CareDP_138.0_SW05.10.exe</a>

**6234 (RM-123) – Flash Chip SPANSION**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_15-05-06_RM-123_(c)_Nokia	RM-123_dp_v_79.0_mcusw03.70.exe
V_04.52_06-07-06_RM-123_(c)_Nokia	RM-123_dp_v_74.1_mcusw04.52.exe
V_04.54_01-08-06_RM-123_(c)_Nokia	
V_04.91_25-09-06_RM-123_(c)_Nokia	RM-123_dp_v_121.0_mcusw04.91.exe
V_05.10_21-12-06_RM-123_(c)_Nokia	RM123_131.0_SW05.10.exe

**6280 (RM-78)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.36_05-12-05_RM-78_(c)_Nokia	RM-78_dp_v_123.0_mcusw03.36.exe
V_03.40_20-12-05_RM-78_(c)_Nokia	RM-78_dp_v_112.0_mcusw03.40.exe
V_03.60_10-02-06_RM-78_(c)_Nokia	RM-78_dp_v_147.0_mcusw03.60.exe
V_03.65_22-03-06_RM-78_(c)_Nokia	RM-78_dp_v_159.0_mcusw03.65.exe
V_03.70_28-03-06_RM-78_(c)_Nokia	RM-78_dp_v_167.0_mcusw03.70.exe
V_03.81_09-05-06_RM-78_(c)_Nokia	RM-78_dp_v_188.0_mcusw03.81.exe
V_05.92_07-09-06_RM-78_(c)_Nokia	RM-78_dp_v_325.0_mcusw05.92.exe
V_05.94_14-11-06_RM-78_(c)_Nokia	RM-78_dp_v_328.0_mcusw05.94.exe
V_05.96_29-11-06_RM-78_(c)_Nokia	RM-78_dp_v_333.0_mcusw05.96.exe
V_06.10_21-12-06_RM-78_(c)_Nokia	RM-78_dp_v_343.0_mcusw06.10.exe
V_06.43_30-03-07_RM-78_(c)_Nokia	RM-78_dp_v_345.0_mcusw06.43.exe

**6300 (RM-217) – Flash Chip SEC xxxxxxxx-ATB**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
* V_04.70_24-01-07_RM-217_(c)_Nokia.	RM-217_DP20_5.371__sw-04.70.exe
* V_04.71_28-02-07_RM-217_(c)_Nokia.	RM-217_DP20_2.10__sw-04.71.exe
* V_05.00_27-04-07_RM-217_(c)_Nokia.	RM-217_DP20_3.00_sw-05.00.exe

**6300 (RM-217) – Flash Chip SEC xxxxxxxx-ATD**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.70_24-01-07_RM-217_(c)_Nokia.	RM-217_DP20_5.371__sw-04.70.exe
V_04.71_28-02-07_RM-217_(c)_Nokia.	RM-217_DP20_2.10__sw-04.71.exe
V_05.00_27-04-07_RM-217_(c)_Nokia.	RM-217_DP20_3.00_sw-05.00.exe

**6300 (RM-217) – Flash Chip SPANSION**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.20_05-12-06_RM-217_(c)_Nokia.	RM-217_DP20_1.00__sw-04.20.exe
V_04.70_24-01-07_RM-217_(c)_Nokia.	RM-217_DP20_5.371__sw-04.70.exe
V_04.71_28-02-07_RM-217_(c)_Nokia.	RM-217_DP20_2.10__sw-04.71.exe
V_05.00_27-04-07_RM-217_(c)_Nokia.	RM-217_DP20_3.00_sw-05.00.exe

**6300b (RM-222) – Flash Chip SEC xxxxxxxx-ATB**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
* V_04.70_24-01-07_RM-217_(c)_Nokia.	RM-217_DP20_5.371__sw-04.70.exe
* V_04.71_28-02-07_RM-217_(c)_Nokia.	RM-217_DP20_2.10__sw-04.71.exe
* V_05.00_27-04-07_RM-217_(c)_Nokia.	RM-217_DP20_3.00_sw-05.00.exe

**6300b (RM-222) – Flash Chip SEC xxxxxxxx-ATD**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.70_24-01-07_RM-222_(c)_Nokia.	
V_04.71_28-02-07_RM-222_(c)_Nokia.	RM-222_DP20_1.10__sw-04.20_4.71.exe
V_05.00_27-04-07_RM-222_(c)_Nokia.	

**6300b (RM-222) – Flash Chip SPANSION**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.20_05-12-06_RM-222_(c)_Nokia.	RM-222_DP20_1.00_sw-04.20.exe
V_04.70_24-01-07_RM-222_(c)_Nokia.	
V_04.71_28-02-07_RM-222_(c)_Nokia.	RM-222_DP20_1.10__sw-04.20_4.71.exe
V_05.00_27-04-07_RM-222_(c)_Nokia.	

**7370 (RM-70)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.13_16-05-06_RM-70_(c)_Nokia.	RM-70_DP20_5.00__sw-04.13.exe

**7373 (RM-209)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.90_06-10-06_RM-209_(c)_Nokia.	RM-209_DP20_1.00__sw-03.90.exe
V_04.70_24-01-07_RM-209_(c)_Nokia.	RM-209_DP20_2.00_sw-04.70_04.71.exe
V_04.71_28-02-07_RM-209_(c)_Nokia.	RM-209_DP20_2.00_sw-04.70_04.71.exe

**7390 (RM-140)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.84_23-10-06_RM-140_(c)_Nokia	RM-140_dp_v_121.0_mcusw03.84.exe

**E50-1 (RM-170)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_2.26.01_04-07-06_RM-170_(c)_Nokia.	RM-170_EMEA_LTA_DP2.0_v1.0_SW06.27.01.exe
V_3.37.23_11-10-06_RM-170_(c)_Nokia.	RM-170_EMEA_LTA_06.41.3.0_v3.0.exe

**E50-2 (RM-171)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_2.26.01_04-07-06_RM-171_(c)_Nokia.	RM-171_EMEA_LTA_DP2.0_v1.0_SW06.27.01.exe
V_3.37.23_11-10-06_RM-171_(c)_Nokia.	RM-171_EMEA_LTA_06.41.3.0_v3.0.exe

**E61 (RM-89)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_3.0533.6_31-10-06_RM-89_(c)_Nokia.	RM-89_3.0_EMEA_306330904.exe

**E65 (RM-208)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_1.0615.25_10-01-07_RM-208_(c)_Nokia	RM-208_apac_1.0633.18.01_v1.0.exe

**N71 (RM-67)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
* <a href="#">V_05wk33v23.5_04-04-06_RM-67_(c)_Nokia.</a>	<a href="#">RM-67_Phone_Data_Package_EMEA_1_0.exe</a>

**N73 (RM-133)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05wk47v28.1_22-06-06_RM-133_(c)_Nokia.	RM-133_EMEA_2.0628.0.0.1_v1.0.exe
V_05wk47v28.3_26-07-06_RM-133_(c)_Nokia.	RM-133_EMEA_2.0628.0.0.3_v2.0.exe
V_05wk47v38.1_19-01-07_RM-133_(c)_Nokia.	RM-133_ME_APAC_3.0705.1.0.31_v2.0.exe
V_05wk47v46.3_04-06-07_RM-133_(c)_Nokia.	RM-133_APAC_4.0723.2.0.1_v7.0.exe
V_05wk47v48.3_02-07-07_RM-133_(c)_Nokia.	RM-133_ME_EMEA_4.0727.2.2.1_v3.0.exe

**N75 (RM-128)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_06wk15v37_08-03-07_RM-128_(c)_Nokia.	Nokia_firmware_RM-128_LTA_NAM_10.2.055_v1.0.exe

**N80 (RM-92)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05wk33v33.1_22-06-06_RM-92_(c)_Nokia.	RM-92_EMEA_PR_dp_v13.00_SW4.0623.0.41.exe

**N91 (RM-43)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_w33_06w16v2_20-04-06_RM-43_(c)_Nokia.	RM-43_EMEA_10.00.exe
V_w33_06w24v4_13-09-06_RM-43_(c)_Nokia.	RM-43_EMEA_30.00.exe

**N95 (RM-159)**

V_06wk41v18.4_13-03-07_RM-159_(c)_Nokia	RM-159_EURO_10.0.018_v1.0.exe
V_06wk41v23.4_17-04-07_RM-159_(c)_Nokia	RM-159_EURO_11.0.026_v2.0.exe
V_06wk41v31_05-06-07_RM-159_(c)_Nokia	RM-159_EURO_12.0.013_v3.0.exe