

## Supported Versions for BB5 Box with Firmware version 15

(total 255 supported models/versions)

\* - New model/version added from previous firmware

+ - Improved unlocking trigger from previous firmware

### 3109c (RM-274)

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_05.30_16-05-07_RM-274_(c)_Nokia.	RM-274_DP20_1.00_sw-05.30.exe
V_05.50_14-08-07_RM-274_(c)_Nokia.	RM-274_DP20_2.00_sw-05.50.exe

### 3110c (RM-237)

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_04.91_03-04-07_RM-237_(c)_Nokia.	RM-237_DP20_1.00_sw-04.91.exe
V_05.01_21-05-07_RM-237_(c)_Nokia.	RM-237_DP20_2.00_sw-05.01.exe
V_05.50_14-08-07_RM-237_(c)_Nokia.	RM-237_DP20_3.00_sw-05.50.exe

### 3250 (RM-38)

MCU firmware version	Nokia Data Package file for flashing
V_04.21_16-02-07_RM-38_(c)_Nokia.	RM38_EMEA_APAC_LTA_13.00.exe

### 5200 (RM-174) – Flash Chip SEC xxxxxxxx-ATB

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_03.70_22-09-06_RM-174_(c)_Nokia.	RM-174_DP20_1.00_sw-03.70.exe
V_03.92_13-10-06_RM-174_(c)_Nokia.	RM-174_DP20_2.00_sw-03.92.exe
V_03.93_20-11-06_RM-174_(c)_Nokia.	RM-174_DP20_2.30_sw-03.92.exe
V_04.71_28-02-07_RM-174_(c)_Nokia.	RM-174_DP20_3.00_sw-04.71.exe
V_05.00_27-04-07_RM-174_(c)_Nokia.	RM-174_DP20_4.00_sw-05.00.exe
V_05.51_05-09-07_RM-174_(c)_Nokia.	RM-174_DP20_5.00_sw-05.51.exe

**5200 (RM-174) – Flash Chip SEC xxxxxxxx-ATD****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_22-09-06_RM-174_(c)_Nokia.	RM-174_DP20_1.00__sw-03.70.exe
V_03.92_13-10-06_RM-174_(c)_Nokia.	RM-174_DP20_2.00__sw-03.92.exe
V_03.93_20-11-06_RM-174_(c)_Nokia.	RM-174_DP20_2.30__sw-03.92.exe
V_04.71_28-02-07_RM-174_(c)_Nokia.	RM-174_DP20_3.00__sw-04.71.exe
V_05.00_27-04-07_RM-174_(c)_Nokia.	RM-174_DP20_4.00__sw-05.00.exe
V_05.51_05-09-07_RM-174_(c)_Nokia.	RM-174_DP20_5.00__sw-05.51.exe

**5200b (RM-181) – Flash Chip SEC xxxxxxxx-ATB****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_22-09-06_RM-174_(c)_Nokia.	
V_03.92_13-10-06_RM-181_(c)_Nokia.	
V_03.93_20-11-06_RM-174_(c)_Nokia.	
V_04.71_28-02-07_RM-181_(c)_Nokia.	
V_05.00_27-04-07_RM-181_(c)_Nokia.	
V_05.51_05-09-07_RM-174_(c)_Nokia.	RM-174_DP20_5.00__sw-05.51.exe

**5200b (RM-181) – Flash Chip SEC xxxxxxxx-ATD****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_22-09-06_RM-174_(c)_Nokia.	
V_03.92_13-10-06_RM-181_(c)_Nokia.	
V_03.93_20-11-06_RM-174_(c)_Nokia.	
V_04.71_28-02-07_RM-181_(c)_Nokia.	
V_05.00_27-04-07_RM-181_(c)_Nokia.	
V_05.51_05-09-07_RM-174_(c)_Nokia.	RM-174_DP20_5.00__sw-05.51.exe

### 5300 (RM-146) – Flash Chip SEC xxxxxxxx-ATB

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_03.50_14-09-06_RM-146_(c)_Nokia.	RM-146_DP20_1.00__sw-03.50.exe
V_03.51_20-09-06_RM-146_(c)_Nokia.	RM-146_DP20_1.20__sw-03.50.exe
V_03.92_13-10-06_RM-146_(c)_Nokia.	RM-146_DP20_2.00__sw-03.92.exe
V_03.93_20-11-06_RM-146_(c)_Nokia.	RM-146_DP20_2.30__sw-03.92.exe
V_04.51_11-01-07_RM-146_(c)_Nokia.	RM-146_DP20_2.20_MCU SW 3.92 & 4.51.exe
V_04.70_24-01-07_RM-146_(c)_Nokia.	RM-146_DP20_3.00__sw-04.70.exe
V_04.71_28-02-07_RM-146_(c)_Nokia.	RM-146_DP20_3.10__sw-04.71.exe
V_05.00_27-04-07_RM-146_(c)_Nokia.	RM-146_DP20_4.00__sw-05.00.exe
V_05.02_05-06-07_RM-146_(c)_Nokia.	RM-146_DP20_2.00__sw-05.02.exe
V_05.50_14-08-07_RM-146_(c)_Nokia.	RM-146_DP20_5.00__sw-05.50_5.51.exe
V_05.51_05-09-07_RM-146_(c)_Nokia.	RM-146_DP20_5.00__sw-05.50_5.51.exe

### 5300 (RM-146) – Flash Chip SEC xxxxxxxx-ATD

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_03.50_14-09-06_RM-146_(c)_Nokia.	RM-146_DP20_1.00__sw-03.50.exe
V_03.51_20-09-06_RM-146_(c)_Nokia.	RM-146_DP20_1.20__sw-03.50.exe
V_03.92_13-10-06_RM-146_(c)_Nokia.	RM-146_DP20_2.00__sw-03.92.exe
V_03.93_20-11-06_RM-146_(c)_Nokia.	RM-146_DP20_2.30__sw-03.92.exe
V_04.51_11-01-07_RM-146_(c)_Nokia.	RM-146_DP20_2.20_MCU SW 3.92 & 4.51.exe
V_04.70_24-01-07_RM-146_(c)_Nokia.	RM-146_DP20_3.00__sw-04.70.exe
V_04.71_28-02-07_RM-146_(c)_Nokia.	RM-146_DP20_3.10__sw-04.71.exe
V_05.00_27-04-07_RM-146_(c)_Nokia.	RM-146_DP20_4.00__sw-05.00.exe
V_05.02_05-06-07_RM-146_(c)_Nokia.	RM-146_DP20_2.00__sw-05.02.exe
V_05.50_14-08-07_RM-146_(c)_Nokia.	RM-146_DP20_5.00__sw-05.50_5.51.exe
V_05.51_05-09-07_RM-146_(c)_Nokia.	RM-146_DP20_5.00__sw-05.50_5.51.exe

**5300b (RM-147) – Flash Chip SEC xxxxxxxx-ATB****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.50_14-09-06_RM-147_(c)_Nokia.	
V_03.51_20-09-06_RM-147_(c)_Nokia.	
V_03.92_13-10-06_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_03.93_20-11-06_RM-146_(c)_Nokia.	
V_04.51_11-01-07_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_04.70_24-01-07_RM-147_(c)_Nokia.	
V_04.71_28-02-07_RM-147_(c)_Nokia.	
V_05.00_27-04-07_RM-147_(c)_Nokia.	
V_05.02_05-06-07_RM-147_(c)_Nokia.	RM-147_DP20_2.00_sw-05.02.exe
V_05.50_14-08-07_RM-147_(c)_Nokia.	
V_05.51_05-09-07_RM-147_(c)_Nokia.	

**5300b (RM-147) – Flash Chip SEC xxxxxxxx-ATD****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.50_14-09-06_RM-147_(c)_Nokia.	
V_03.51_20-09-06_RM-147_(c)_Nokia.	
V_03.92_13-10-06_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_03.93_20-11-06_RM-146_(c)_Nokia.	
V_04.51_11-01-07_RM-147_(c)_Nokia.	RM-147_DP20_1.20_sw-03.50_3.92_4.51.exe
V_04.70_24-01-07_RM-147_(c)_Nokia.	
V_04.71_28-02-07_RM-147_(c)_Nokia.	
V_05.00_27-04-07_RM-147_(c)_Nokia.	
V_05.02_05-06-07_RM-147_(c)_Nokia.	RM-147_DP20_2.00_sw-05.02.exe
V_05.50_14-08-07_RM-147_(c)_Nokia.	
V_05.51_05-09-07_RM-147_(c)_Nokia.	

**5500 (RM-86)**

MCU firmware version	Nokia Data Package file for flashing
V_03.55_23-11-06_RM-86_(c)_Nokia.	

**6085 (RM-198)****Supported ALL versions available today**

MCU firmware version	Nokia Data Package file for flashing
* <a href="#">V_03.52_09-10-06_RM-198_(c)_Nokia.</a>	<a href="#">RM-198_4.00.exe</a>
* <a href="#">V_03.70_03-11-06_RM-198_(c)_Nokia.</a>	<a href="#">RM-198_7.00.exe</a>
V_03.71_30-11-06_RM-198_(c)_Nokia.	RM-198_7.01.exe
* <a href="#">V_04.11_11-01-07_RM-198_(c)_Nokia.</a>	<a href="#">RM-198_13.exe</a>
* <a href="#">V_04.22_01-03-07_RM-198_(c)_Nokia.</a>	<a href="#">RM-198_13.01.exe</a>
V_04.26_16-03-07_RM-198_(c)_Nokia.	RM-198_CareDP_14.0_APAC_EMEA_US_LTA.exe
* <a href="#">V_04.29_03-05-07_RM-198_(c)_Nokia.</a>	<a href="#">RM-198_CareDP_14.5_US_LTA.exe</a>
* <a href="#">V_04.30_30-08-07_RM-198_(c)_Nokia.</a>	<a href="#">RM-198_CareDP_19.0_NA_LTA.exe</a>
V_05.02_08-05-07_RM-198_(c)_Nokia.	RM-198_CareDP_17.0_APAC_EMEA.exe
V_05.03_09-08-07_RM-198_(c)_Nokia.	RM-198_CareDP_18.0_EMEA_APAC.exe

**6086 (RM-188)****Supported ALL versions available today**

MCU firmware version	Nokia Data Package file for flashing
V_03.51_15-02-07_RM-188_(c)_Nokia.	RM-188_EMEA_LTA_NA_2.00.exe
* <a href="#">V_03.52_28-03-07_RM-188_(c)_Nokia.</a>	<a href="#">RM-188_CareDP_3.0_EMEA_LTA_NA.exe</a>
V_05.03_03-08-07_RM-188_(c)_Nokia.	RM-188_CareDP_5.0_EMEA.exe

**6086b (RM-260)****Supported ALL versions available today**

MCU firmware version	Nokia Data Package file for flashing
* <a href="#">V_13.51_18-04-07_RM-260_(c)_Nokia.</a>	<a href="#">RM-260_CareDP_2.0_TMO.exe</a>
* <a href="#">V_15.02_04-06-07_RM-260_(c)_Nokia.</a>	<a href="#">RM-260_CareDP_3.0_TMO.exe</a>
* <a href="#">V_15.04_30-08-07_RM-260_(c)_Nokia.</a>	<a href="#">RM-260_CareDP_3.1_TMO.exe</a>

**6125 (RM-178) – Flash Chip SEC xxxxxxxx-ATB****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
* V_03.51_03-04-06_RM-178_(c)_Nokia.	RM-178_EMEA_APAC_LTA_2.00.exe
V_03.71_31-05-06_RM-178_(c)_Nokia.	RM-178_EMEA_APAC_LTA_11.00.exe
V_03.72_10-08-06_RM-178_(c)_Nokia.	RM-178_EMEA_APAC_LTA_13.00.exe
V_04.20_13-11-06_RM-178_(c)_Nokia.	RM-178_EMEA_APAC_LTA_14.00.exe
V_05.43_24-05-07_RM-178_(c)_Nokia.	RM-178_CareDP_17.0_EMEA_APAC.exe

**6125 (RM-178) – Flash Chip SEC xxxxxxxx-ATD****Supported ALL versions available today****(firmwares lower than 04.20 are not compatible with SEC ATD chips)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.20_13-11-06_RM-178_(c)_Nokia.	RM-178_EMEA_APAC_LTA_14.00.exe
V_05.43_24-05-07_RM-178_(c)_Nokia.	RM-178_CareDP_17.0_EMEA_APAC.exe

**6126/6133 (RM-126)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.24_04-07-06_RM-126_(c)_Nokia.	RM-126_DP20_1.00__sw-04.24.exe
V_05.61_14-12-06_RM-126_(c)_Nokia.	RM-126_DP20_2.00__sw-05.60_05.61.exe

**6131 (RM-115)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05.50_20-09-06_RM-115_(c)_Nokia.	RM-115_DP20_3.00__sw-05.50.exe
V_06.10_16-02-07_RM-115_(c)_Nokia.	RM-115_DP20_4.00__sw-06.10.exe

## 6136 (RM-199)

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_03.71.2_12-09-06_RM-199_(c)_Nokia.	RM-199_EMEA_5.00.exe
* V_04.01_20-11-06_RM-199_(c)_Nokia.	RM-199_EMEA_7.00.exe
* V_14.01_20-11-06_RM-199_(c)_Nokia.	RM-199_EMEA_7.00.exe
* V_05.21_25-01-07_RM-199_(c)_Nokia.	RM-199_EMEA_8.00.exe
* V_15.21_25-01-07_RM-199_(c)_Nokia.	RM-199_EMEA_8.00.exe

## 6151 (RM-200)

MCU firmware version	Nokia Data Package file for flashing
V_03.91_25-09-06_RM-200_(c)_Nokia	RM-200_dp_v_72.0_mcusw03.91.exe
V_04.10_21-12-06_RM-200_(c)_Nokia	RM-200_dp_v_81_0_mcusw04_10.exe

## 6233 (RM-145) – Flash Chip SEC xxxxxxxx-ETM

MCU firmware version	Nokia Data Package file for flashing
V_05.10_21-12-06_RM-145_(c)_Nokia	RM145_CareDP_138.0_SW05.10.exe

## 6233 (RM-145) – Flash Chip SPANSION

MCU firmware version	Nokia Data Package file for flashing
V_03.70_15-05-06_RM-145_(c)_Nokia	RM-145_dp_v_78.0_mcusw03.70.exe
V_04.52_06-07-06_RM-145_(c)_Nokia	RM-145_dp_v_95.0_mcusw04.52_04.54.exe
V_04.54_01-08-06_RM-145_(c)_Nokia	RM-145_dp_v_95.0_mcusw04.52_04.54.exe
V_04.91_25-09-06_RM-145_(c)_Nokia	RM-145_dp_v_122.0_mcusw04.91.exe
V_05.10_21-12-06_RM-145_(c)_Nokia	RM145_CareDP_138.0_SW05.10.exe

## 6234 (RM-123) – Flash Chip SEC xxxxxxxx-ETM

MCU firmware version	Nokia Data Package file for flashing
V_05.10_21-12-06_RM-145_(c)_Nokia	RM145_CareDP_138.0_SW05.10.exe

**6234 (RM-123) – Flash Chip SPANSION**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.70_15-05-06_RM-123_(c)_Nokia	RM-123_dp_v_79.0_mcusw03.70.exe
V_04.52_06-07-06_RM-123_(c)_Nokia	RM-123_dp_v_74.1_mcusw04.52.exe
V_04.54_01-08-06_RM-123_(c)_Nokia	
V_04.91_25-09-06_RM-123_(c)_Nokia	RM-123_dp_v_121.0_mcusw04.91.exe
V_05.10_21-12-06_RM-123_(c)_Nokia	RM123_131.0_SW05.10.exe

**6280 (RM-78) – Flash Chip SEC xxxxxxxx-ETA****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.36_05-12-05_RM-78_(c)_Nokia	RM-78_dp_v_123.0_mcusw03.36.exe
V_03.40_20-12-05_RM-78_(c)_Nokia	RM-78_dp_v_112.0_mcusw03.40.exe
V_03.41_14-01-06_RM-78_(c)_Nokia	RM-78_dp_v_112.0_mcusw03.40.exe
V_03.60_10-02-06_RM-78_(c)_Nokia	RM-78_dp_v_147.0_mcusw03.60.exe
V_03.65_22-03-06_RM-78_(c)_Nokia	RM-78_dp_v_159.0_mcusw03.65.exe
V_03.70_28-03-06_RM-78_(c)_Nokia	RM-78_dp_v_167.0_mcusw03.70.exe
V_03.81_09-05-06_RM-78_(c)_Nokia	RM-78_dp_v_188.0_mcusw03.81.exe
V_05.92_07-09-06_RM-78_(c)_Nokia	RM-78_dp_v_325.0_mcusw05.92.exe
V_05.94_14-11-06_RM-78_(c)_Nokia	RM-78_dp_v_328.0_mcusw05.94.exe
V_05.96_29-11-06_RM-78_(c)_Nokia	RM-78_dp_v_333.0_mcusw05.96.exe
V_06.10_21-12-06_RM-78_(c)_Nokia	RM-78_dp_v_343.0_mcusw06.10.exe
V_06.43_30-03-07_RM-78_(c)_Nokia	RM-78_dp_v_345.0_mcusw06.43.exe

**6280 (RM-78) – Flash Chip SPANSION****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.36_05-12-05_RM-78_(c)_Nokia	RM-78_dp_v_123.0_mcusw03.36.exe
V_03.40_20-12-05_RM-78_(c)_Nokia	RM-78_dp_v_112.0_mcusw03.40.exe
V_03.41_14-01-06_RM-78_(c)_Nokia	RM-78_dp_v_112.0_mcusw03.40.exe
V_03.60_10-02-06_RM-78_(c)_Nokia	RM-78_dp_v_147.0_mcusw03.60.exe
V_03.65_22-03-06_RM-78_(c)_Nokia	RM-78_dp_v_159.0_mcusw03.65.exe
V_03.70_28-03-06_RM-78_(c)_Nokia	RM-78_dp_v_167.0_mcusw03.70.exe
V_03.81_09-05-06_RM-78_(c)_Nokia	RM-78_dp_v_188.0_mcusw03.81.exe
V_05.92_07-09-06_RM-78_(c)_Nokia	RM-78_dp_v_325.0_mcusw05.92.exe
V_05.94_14-11-06_RM-78_(c)_Nokia	RM-78_dp_v_328.0_mcusw05.94.exe
V_05.96_29-11-06_RM-78_(c)_Nokia	RM-78_dp_v_333.0_mcusw05.96.exe
V_06.10_21-12-06_RM-78_(c)_Nokia	RM-78_dp_v_343.0_mcusw06.10.exe
V_06.43_30-03-07_RM-78_(c)_Nokia	RM-78_dp_v_345.0_mcusw06.43.exe

**6300 (RM-217) – Flash Chip SEC xxxxxxxx-ATB****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_04.20_05-12-06_RM-217_(c)_Nokia.	RM-217_DP20_1.00__sw-04.20.exe
V_04.70_24-01-07_RM-217_(c)_Nokia.	RM-217_DP20_5.371__sw-04.70.exe
V_04.71_28-02-07_RM-217_(c)_Nokia.	RM-217_DP20_2.10__sw-04.71.exe
V_05.00_27-04-07_RM-217_(c)_Nokia.	RM-217_DP20_3.00__sw-05.00.exe
V_05.50_14-08-07_RM-217_(c)_Nokia.	RM-217_DP20_4.00__sw-05.50.exe
V_05.52_09-11-07_RM-217_(c)_Nokia.	RM-217_DP20_4.30__sw-05.52.exe

### 6300 (RM-217) – Flash Chip SEC xxxxxxxx-ATD

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_04.20_05-12-06_RM-217_(c)_Nokia.	RM-217_DP20_1.00__sw-04.20.exe
V_04.70_24-01-07_RM-217_(c)_Nokia.	RM-217_DP20_5.371__sw-04.70.exe
V_04.71_28-02-07_RM-217_(c)_Nokia.	RM-217_DP20_2.10__sw-04.71.exe
V_05.00_27-04-07_RM-217_(c)_Nokia.	RM-217_DP20_3.00__sw-05.00.exe
V_05.50_14-08-07_RM-217_(c)_Nokia.	RM-217_DP20_4.00__sw-05.50.exe
V_05.52_09-11-07_RM-217_(c)_Nokia.	RM-217_DP20_4.30__sw-05.52.exe

### 6300 (RM-217) – Flash Chip SPANSION

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_04.20_05-12-06_RM-217_(c)_Nokia.	RM-217_DP20_1.00__sw-04.20.exe
V_04.70_24-01-07_RM-217_(c)_Nokia.	RM-217_DP20_5.371__sw-04.70.exe
V_04.71_28-02-07_RM-217_(c)_Nokia.	RM-217_DP20_2.10__sw-04.71.exe
V_05.00_27-04-07_RM-217_(c)_Nokia.	RM-217_DP20_3.00__sw-05.00.exe
V_05.50_14-08-07_RM-217_(c)_Nokia.	RM-217_DP20_4.00__sw-05.50.exe
V_05.52_09-11-07_RM-217_(c)_Nokia.	RM-217_DP20_4.30__sw-05.52.exe

### 6300b (RM-222) – Flash Chip SEC xxxxxxxx-ATB

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_04.20_05-12-06_RM-222_(c)_Nokia.	
V_04.70_24-01-07_RM-222_(c)_Nokia.	
V_04.71_28-02-07_RM-222_(c)_Nokia.	RM-222_DP20_2.10__sw-04.71.exe
V_05.00_27-04-07_RM-222_(c)_Nokia.	
V_05.50_14-08-07_RM-222_(c)_Nokia.	
V_05.52_09-11-07_RM-222_(c)_Nokia.	

### 6300b (RM-222) – Flash Chip SEC xxxxxxxx-ATD

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_04.20_05-12-06_RM-222_(c)_Nokia.	
V_04.70_24-01-07_RM-222_(c)_Nokia.	
V_04.71_28-02-07_RM-222_(c)_Nokia.	RM-222_DP20_1.10__sw-04.20_4.71.exe
V_05.00_27-04-07_RM-222_(c)_Nokia.	
V_05.50_14-08-07_RM-222_(c)_Nokia.	
V_05.52_09-11-07_RM-217_(c)_Nokia.	

### 6300b (RM-222) – Flash Chip SPANSION

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_04.20_05-12-06_RM-222_(c)_Nokia.	RM-222_DP20_1.00_sw-04.20.exe
V_04.70_24-01-07_RM-222_(c)_Nokia.	
V_04.71_28-02-07_RM-222_(c)_Nokia.	RM-222_DP20_1.10__sw-04.20_4.71.exe
V_05.00_27-04-07_RM-222_(c)_Nokia.	
V_05.50_14-08-07_RM-217_(c)_Nokia.	
V_05.52_09-11-07_RM-217_(c)_Nokia.	

### 7370 (RM-70)

MCU firmware version	Nokia Data Package file for flashing
V_04.13_16-05-06_RM-70_(c)_Nokia.	RM-70_DP20_5.00__sw-04.13.exe

### 7373 (RM-209)

Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_03.90_06-10-06_RM-209_(c)_Nokia.	RM-209_DP20_1.00__sw-03.90.exe
V_04.70_24-01-07_RM-209_(c)_Nokia.	RM-209_DP20_2.00_sw-04.70_04.71.exe
V_04.71_28-02-07_RM-209_(c)_Nokia.	RM-209_DP20_2.00_sw-04.70_04.71.exe
V_05.00_27-04-07_RM-209_(c)_Nokia.	RM-209_DP20_3.00_sw-05.00.exe
V_05.50_14-08-07_RM-209_(c)_Nokia.	RM-209_DP20_4.00__sw-05.50.exe

**7390 (RM-140)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.84_23-10-06_RM-140_(c)_Nokia	RM-140_dp_v_121.0_mcusw03.84.exe
V_04.51_29-11-06_RM-140_(c)_Nokia	RM-140_dp_v_138.0_mcusw04.51.exe

**8600 (RM-164)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_03.52_24-05-07_RM-164_(c)_Nokia.	RM-164_CareDP_3.0_GLOBAL.exe

**E50-1 (RM-170)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_2.26.01_04-07-06_RM-170_(c)_Nokia.	RM-170_EMEA_LTA_DP2.0_v1.0_SW06.27.01.exe
V_3.37.23_11-10-06_RM-170_(c)_Nokia.	RM-170_EMEA_LTA_06.41.3.0_v3.0.exe
V_4.41.41_28-06-07_RM-170_(c)_Nokia.	RM-170_emea_lta_07.36.0.0_v6.0.exe

**E50-2 (RM-171)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_2.26.01_04-07-06_RM-171_(c)_Nokia.	RM-171_EMEA_LTA_DP2.0_v1.0_SW06.27.01.exe
V_3.37.23_11-10-06_RM-171_(c)_Nokia.	RM-171_EMEA_LTA_06.41.3.0_v3.0.exe
V_4.41.41_28-06-07_RM-171_(c)_Nokia.	RM-171_emea_lta_07.36.0.0_v6.0.exe

**E50-3 (RM-172)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_2.26.01_04-07-06_RM-172_(c)_Nokia.	RM-172_EMEA_LTA_DP2.0_v1.0_SW06.27.01.exe
V_3.37.23_11-10-06_RM-172_(c)_Nokia.	RM-172_EMEA_LTA_06.41.3.0_v3.0.exe
V_4.41.41_28-06-07_RM-172_(c)_Nokia.	RM-172_emea_lta_07.36.0.0_v6.0.exe

**E60 (RM-49)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_1.0533.47.12_28-03-06_RM-49_(c)_Nokia.	RM-49_1.0_106100215.exe
V_2.0533.47.5_26-06-06_RM-49_(c)_Nokia.	RM-49_2.0_emea_206180605.exe

**E61 (RM-89)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_3.0533.6_31-10-06_RM-89_(c)_Nokia.	RM-89_3.0_EMEA_306330904.exe

**E61i (RM-227)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_1.0615.31_12-02-07_RM-227_(c)_Nokia.	RM-227_APAC_1.0633.22.05_v1.0.exe

**E62 (RM-88)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
Vp_2.0618.06.17_10-08-06_RM-88_(c)_Nokia._	RM-88_DP1.0_APAC_18.06.17.exe

**E65 (RM-208)****Supported ALL versions available today**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_1.0615.25_10-01-07_RM-208_(c)_Nokia	RM-208_apac_1.0633.18.01_v1.0.exe
V_1.0615.25.1_31-05-07_RM-208_(c)_Nokia.	RM-208_EMEA_1.0633.58.03_v1.83.exe
V_2.0615.10_22-08-07_RM-208_(c)_Nokia.	RM-208_EMEA_2.0633.62.03_v2.0.exe
V_2.0615.30_13-09-07_RM-208_(c)_Nokia.	RM-208_emea_lta_2.0633.65.01_v4.0.exe

**N71 (RM-67)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05wk33v23.5_04-04-06_RM-67_(c)_Nokia.	RM-67_Phone_Data_Package_EMEA_1_0.exe

### N73-1 (RM-133)

#### Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_05wk47v28.1_22-06-06_RM-133_(c)_Nokia.	RM-133_EMEA_2.0628.0.0.1_v1.0.exe
V_05wk47v28.3_26-07-06_RM-133_(c)_Nokia.	RM-133_EMEA_2.0628.0.0.3_v2.0.exe
V_05wk47v32.1_01-09-06_RM-133_(c)_Nokia.	RM-133_APAC_3.0636.0.0.6_v2.0.exe
V_05wk47v34.1_05-10-06_RM-133_(c)_Nokia.	RM-133_EMEA_3.0638.0.0.1_v3.0.exe
V_05wk47v38_20-11-06_RM-133_(c)_Nokia.	RM-133_EMEA_3.0649.0.0.1_v4.0.exe
V_05wk47v38.1_19-01-07_RM-133_(c)_Nokia.	RM-133_EMEA_3.0704.1.0.1_v5.0.exe
V_05wk47v38.2_27-03-07_RM-132_(c)_Nokia.	RM-133_EMEA_3.0713.1.0.2_v6.0.exe
V_05wk47v46.3_04-06-07_RM-133_(c)_Nokia.	RM-133_APAC_4.0723.2.0.1_v7.0.exe
V_05wk47v48_26-06-07_RM-133_(c)_Nokia.	RM-133_EMEA_4.0726.2.0.1_v7.0.exe
V_05wk47v48.3_02-07-07_RM-133_(c)_Nokia.	RM-133_ME_EMEA_4.0727.2.2.1_v3.0.exe
V_05wk47v50.3_16-08-07_RM-133_(c)_Nokia.	RM-133_EMEA_4.0734.2.0.2_v8.0.exe
V_05wk47v50.5_16-10-07_RM-133_(c)_Nokia.	RM-133_EMEA_4.0743.2.8.2_v9.00.exe
V_05wk47v51.3_24-08-07_RM-133_(c)_Nokia.	RM-133_ME_EMEA_4.0734.2.2.1_v4.0.exe
V_05wk47v51.4_29-08-07_RM-133_(c)_Nokia.	RM-133_EMEA_4.0735.3.0.2_v10.0.exe
V_05wk47v51.5_29-08-07_RM-133_(c)_Nokia.	RM-133_ME_EMEA_4.0736.3.2.1_v5.0.exe
V_05wk47v51.7_07-09-07_RM-133_(c)_Nokia.	RM-133_EMEA_4.0736.2.0.1_v7.08.exe

### N73-5 (RM-132)

#### Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_05wk47v28.3_04-08-06_RM-132_(c)_Nokia.	RM-132_AMERICAS_2.0628.0.0.3_v2.0.exe
V_05wk47v34.1_05-10-06_RM-132_(c)_Nokia.	RM-132_AMERICAS_3.0638.0.0.1_v3.0.exe
V_05wk47v38_20-11-06_RM-132_(c)_Nokia.	RM-132_AMERICAS_3.0649.0.0.1_v4.0.exe
V_05wk47v38.2_27-03-07_RM-132_(c)_Nokia.	RM-132_AMERICAS_3.0713.1.1.2_v5.0.exe
V_05wk47v48_26-06-07_RM-132_(c)_Nokia.	RM-132_AMERICAS_4.0726.2.1.1_v6.0.exe

### N75 (RM-128)

MCU firmware version	Nokia Data Package file for flashing
V_06wk15v37_08-03-07_RM-128_(c)_Nokia.	RM-128_LTA_NAM_10.2.055_v1.0.exe

**N80-1 (RM-92)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05wk33v29_28-04-06_RM-92_(c)_Nokia.	RM-92_EMEA_PR_dp_v12.00_SW3.0617.0.6.exe
V_05wk33v29.2_17-05-06_RM-92_(c)_Nokia.	RM-92_EMEA_PR_dp_v12.04_SW3.0618.0.2.exe
V_05wk33v33.1_22-06-06_RM-92_(c)_Nokia.	RM-92_EMEA_PR_dp_v13.00_SW4.0623.0.41.exe
V_05wk33v33.2_21-11-06_RM-92_(c)_Nokia.	RM-92_EMEA_PR_dp_v16.00_SW4.0623.0.47.exe
V_05wk33v40_11-12-06_RM-92_(c)_Nokia.	RM-92_EMEA_PR_dp_v17.00_SW4.0707.0.7.exe
V_05wk33v42_07-05-07_RM-92_(c)_Nokia.	RM-92_EMEA_PR_dp_v18.0_SW5.0719.0.2.exe
V_05wk33v46_18-06-07_RM-92_(c)_Nokia.	RM-92_APAC_PR_dp_v18.0_SW5.0725.0.1.exe

**N80-3 (RM-91)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_05wk33v29_28-04-06_RM-91_(c)_Nokia.	RM-91_EMEA_PR_dp_v12.00_SW3.0617.0.6.exe
V_05wk33v29.2_17-05-06_RM-91_(c)_Nokia.	RM-91_EMEA_PR_dp_v12.04_SW3.0618.0.2.exe
V_05wk33v33.1_22-06-06_RM-91_(c)_Nokia.	RM-91_EMEA_PR_dp_v13.00_SW4.0623.0.41.exe
V_05wk33v33.2_21-11-06_RM-92_(c)_Nokia.	RM-91_EMEA_PR_dp_v16.00_SW4.0623.0.47.exe
V_05wk33v40_11-12-06_RM-91_(c)_Nokia.	RM-91_EMEA_PR_dp_v17.00_SW4.0707.0.7.exe
V_05wk33v42_07-05-07_RM-91_(c)_Nokia.	RM-91_EMEA_PR_dp_v18.0_SW5.0719.0.2.exe
V_05wk33v46_18-06-07_RM-92_(c)_Nokia.	RM-91_APAC_PR_dp_v18.0_SW5.0725.0.1.exe

**N91-1 (RM-43)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_w33_06w16v2_20-04-06_RM-43_(c)_Nokia.	RM-43_EMEA_10.00.exe
V_w33_06w24v4_13-09-06_RM-43_(c)_Nokia.	RM-43_EMEA_30.00.exe

**N91-5 (RM-158)**

<b>MCU firmware version</b>	<b>Nokia Data Package file for flashing</b>
V_w33_06w16v2_20-04-06_RM-43_(c)_Nokia.	RM-43_EMEA_10.00.exe
V_w33_06w24v4_13-09-06_RM-43_(c)_Nokia.	RM-43_EMEA_30.00.exe

## N93 (RM-55)

### Supported ALL versions available today

MCU firmware version	Nokia Data Package file for flashing
V_05wk47v28.2_03-07-06_RM-55_(c)_Nokia.	RM-55_DP2.0_v2.0_EMEA_SW11.0.034.exe
* <a href="#">V_05wk47v35.1_13-10-06_RM-55_(c)_Nokia.</a>	<a href="#">RM-55_DP2.0_v3.0_EMEA_SW20.0.058.exe</a>

## N95 (RM-159)

### Supported ALL versions available today

V_06wk41v18.4_13-03-07_RM-159_(c)_Nokia	RM-159_EURO_10.0.018_v1.0.exe
V_06wk41v23.4_17-04-07_RM-159_(c)_Nokia	RM-159_EURO_11.0.026_v2.0.exe
V_06wk41v31_05-06-07_RM-159_(c)_Nokia	RM-159_EURO_12.0.013_v3.0.exe
V_06wk41v31.1_09-07-07_RM-159_(c)_Nokia	RM-159_DP_12.0.014_v4.0.exe
V_06wk41v43.1_15-10-07_RM-159_(c)_Nokia	RM-159_EURO_20.0.015_v4.0.exe